

The MINERvA Operations Report

All Experimenters Meeting

Howard Budd, University of Rochester
Oct 6, 2014



Water Leak



- On Sep 29 A water leak appeared above the MINERvA detector.
 - This leak was in the same place that happened during the Easter 2011 leak. This leak is at the downstream end of the MINERvA detector where the bridge is located.
 - The roof does not extend over the bridge.
 - Water dripped onto the bridge and bounced onto the FEB causing some FEBs to fail.



Water Leak



- We assume that the drain of the drip pan above the detector got clogged, filled up and overflowed.
- Bill Lee hit the pan with a pole and the water leak stopped, as the drain of the pan may have cleared .
- 2 FEB replacements were required to get the detector running
- Bill Moorhouse & John Chyllo checked the drip pan the next day and it was clear. They are re-evaluating the procedure to see if additional checks would have found this problem earlier.



Firmware Upgrades



- Starting this week, we will upgrade the CROC-E firmware.
 - We will turn the detector off
 - We will also need to turn it off on Oct 9 for the Oct 10 power outage
 - The CROC-Es will be brought to the 14th floor for the upgrade
 - After about 3 working days the CROC-Es will be reinstalled in the VME crate for the MINERvA detector
 - After the reinstallation of the CROC-E, we will turn the detector back on.



CROC-E Firmware Upgrade



- The firmware upgrade for the CROC-Es.
 - Checks the CRC word
 - Goal: The CRC word (cyclic redundancy check) for all the frames will be passed to the offline to check that there is no problem with the header & data.
 - Requires changes to the DAQ & offline.
 - Should the communication line of the FEB chain fail, a feature which causes error lights to go on a FEB which causes the problem as long as the clock is being passed through the chain.
 - Right now usually the error lights go on, but not always. The software will sometime tell you which FEB fails, but often the software is wrong.



Firmware Upgrades



- Enable the CROC-E firmware to be upgraded without pulling the CROC-Es out of the VME crate.
- We would like to thank – Christian Gingu, Boris Baldin, Paul Rubinov, Donatella Torretta, & Bill Badgett.



DAQ Computer Upgrade



- Two new computers are installed in the DAQ Rack, one of our 2 racks which run the experiment.
- After the installation of the CROC-Es we plan on connecting up one of the computers to our two VME racks and run the detector from this computer.
- Assuming this works the plan is to have one of these two computers as our DAQ computer.
 - The present DAQ computers will be left in place for at least 1 month so we can go back to them if needed.



ROC West



- We have started doing our on-site weekday shifts in the ROCW
- 40% of shifts still are done at remote sites
- We are verifying the setup in the ROCW will work for MINERvA shifts
 - Full functionality not yet achieved but is on the way



Half-Intensity Request



- Our special run request is
 - $12\text{E}12$ POT/pulse (over 6 batches)
 - Integrate $2.0\text{E}18$ POT in that mode
- This will be useful to evaluate intensity-dependent effects
- Earlier data set (2 days of $2\text{E}12$ POT/pulse in late November) has been useful but does not have high enough statistics to fully quantify rate dependence.